## COMPUTER TO SCREEN MODEL CTS

## No Film Required - Just Print the Image Directly on the Screen & Expose!

- Consistency of Wax Gives Superior Results
- High Density of Wax Lets You Fully Harden Screen
- Repeatability Saves
  Registration Set Up Time
- Robust Construction
- Proven Track Record

Faster turn around times Reduced exposure times Precise registration Reduced handling Reduction in labor cost No Film or Film Storage

**FASTER PRESS SETUP** 



## **INCLUDES:**

- Print Head technology with phase-change solid ink (wax) to enable better image detail, density, and consistency.
- (2) PC with easy, intuitive operating controls.
- (3) Compatible with any RIP that can output 1 bit uncompressed TIFF File at 600 DPI or Douthitt can package RIP with unit. Either way, files can be automatically added to print queue after ripping via your Ethernet network.
- (4) Air clamp assembly with convenient foot switch standard on CTS52. Optional on CTS30.

Model	Max Screen*	Max Image	Floor Space	Crated Weight	
CTS30 CTS52	25 x 36 54 x 46	_0.120	37 x 52 37 x 78	925 lbs. 1240 lbs.	

<sup>\*</sup>Max screen can be larger than listed depending on image area

Electrical: 120V. Requires compressed air.